PSC NO: 121 ELECTRICITY NEW YORK STATE ELECTRIC & GAS CORPORATION Initial Effective Date: 01/01/07

Leaf: 58 Revision: 4 Superseding Revision: 3

SERVICE CLASSIFICATION NO. 3 (Cont'd.)

Other Facility Charges: (Monthly Rate)

Charges will apply for all rate choices described in this Service Classification.

	Facility Charge	Energy Charge	Total
Pole Installed by the Corporation Solely for Street			
Lighting Service***			
Standard Wood Pole	\$9.92	n/a	\$9.92
Wood Pole - high mount use (45' or greater)	27.15	n/a	27.15
Steel Pole*	4.39	n/a	4.39
Square Steel Pole 30'*	15.95	n/a	15.95
Aluminum Pole 16' and under	5.98	n/a	5.98
Alum. Pole over 16' installed prior to	15.87	n/a	15.87
August 1, 1987			
Alum. Pole over 16' direct embedded	15.87	n/a	15.87
installed after July 31, 1987	10107		10107
Alum. Pole over 16' pedestal mounted	23.70	n/a	23.70
Concrete Pole*	4.99	n/a	4.99
Laminated Wood Pole*	3.99	n/a	3.99
Fiberglass Pole 18' and under	5.57	n/a	5.57
Fiberglass Pole 18' to 22'	7.58	n/a	7.58
Center Bored Wood Pole* - (no longer	8.97	n/a	8.97
available)	0.97	ii/a	0.77
Concrete Base for pedestal mounted poles	21.05	n/a	21.05
Screw-in steel base for pedestal mounted	21.05	11/ a	21.03
poles:			
Light Duty	13.05	n/a	13.05
Heavy Duty	15.05	n/a n/a	16.61
neavy Duty	10.01	II/a	10.01
Special Brackets			
Standard Bracket - 16' and over	\$2.34	n/a	\$2.34
Bracket Allowance*	(0.62)	n/a	(0.62)
Bracket for post-top use on wood poles*	0.40	n/a	0.40
Circuit Control			
Group Controllers	\$2.99	n/a	\$2.99
3000 Watt Photo Cell	1.99	n/a	1.99
Circuits (Per Trench Foot**)			
Cable and Conduit	\$0.0778	n/a	\$0.0778
Direct Burial Cable	0.0666	n/a	0.0666
Cable Only (Conduit Supplied by Customer)	0.0355	n/a n/a	0.0000
Underground Circuits*	0.0333	n/a n/a	0.0355
Onderground Circuits	0.0473	11/ a	0.0475

**Trench foot is defined as the distance from one standard to another standard, handhole, or transformer.

***Except for a limited number of grandfathered poles with bases, charges for poles are based on gross pole length prior to installation, not the visible mounting height of the luminaire above the finished grade.

Issued in compliance with order in Case No. 05-E-1222 dated 08/23/06.

Issued by: James A. Lahtinen, Vice President - Rates & Regulatory Economics, Binghamton, NY