

PSC NO: 3 TELEPHONE
ALLTEL New York, Inc.
Initial Effective Date: 5/30/03

Section: 6 Leaf: 31
Revision: 0
Superseding Revision:

SECTION 6 - MISCELLANEOUS SERVICES

O. 911 PRIVATE SWITCH/AUTOMATIC LOCATION IDENTIFICATION (PS/ALI) SERVICE (Continued)

2. Regulations (Continued)

- E. The PBX switch owner/operator must install a minimum of two (2) private E9-1-1 local channels (except for PRI and BRI) with the following specifications:
- (1) This voice grade local channel provides for a communications path between the demarcation point at the PBX customer premises and the E9-1-1 SRU tandem office serving the count where the main PBX system is physically located.
 - (2) The PBX switch owner/operator is responsible for determining that their terminal equipment is compatible with this local channel.
 - (3) Supervision on this ALLTEL 9-1-1 PS/ALI service local channel will be loop reverse battery. The battery source is located in ALLTEL's E9-1-1 SRU tandem office and will be a nominal -48VDC (-42.75VDC to -56.5 VDC).
 - (4) The PBX will signal an off hook (or seizure) by providing a loop closure across tip (+) and ring (-) with a maximum resistance of 670 ohms. ALLTEL's E9-1-1 SRU tandem office will instruct the PBX to forward the calling station's number (ANI) information by a battery reversal wink start signal.
 - (5) Additional regulations may be applicable as described in ALLTEL's Private Line Services Tariff.
- F. Service charges as specified elsewhere in this Tariff, are applicable.
- G. General Regulations as specified elsewhere in this Tariff will also apply to this service offering.
- H. This service is offered solely as an aid in handling emergency 9-1-1 assistance calls in connection with fire, police and other emergencies and does not create any relationship or obligation, direct or indirect, to any person other than the PBX customer contracting for ALLTEL 9-1-1 PS/ALI service. The Provision of ALLTEL 9-1-1 PS/ALI service by ALLTEL shall not be interpreted, construed, or regarded either expressly or implied, as being for the benefit of or creating any Company obligation toward any third person or legal entity other than the PBX customer.
- I. The rates charged for ALLTEL 9-1-1 PS/ALI service do not contemplate the constant monitoring or inspection of facilities to discover errors, defects and malfunctions in the service, nor does ALLTEL undertake such responsibility. The PBX customer shall make such operational tests as, in the judgement the PBX customer, are required to determine whether the service is functioning properly for its use. The PBX customer shall promptly notify ALLTEL in the event that the service is not functioning properly.

Issued by: Vice President, State Government Affairs, Little Rock, Arkansas