Received: 05/14/1999 Status: CANCELLED Effective Date: 05/17/1999

..DID: 8626

..TXT: PSC NO: 9 GAS LEAF: 317

COMPANY: CONSOLIDATED EDISON COMPANY OF NEW YORK, INC. REVISION: 1

INITIAL EFFECTIVE DATE: 05/17/99 SUPERSEDING REVISION: 0 STAMPS: Issued in compliance with order in C. 98-G-0122 dated March 16, 1999

Cancelled by 2 Rev. Leaf No. 317 Effective 08/01/2000

RECEIVED: 05/14/99 STATUS: Cancelled EFFECTIVE: 05/17/99

SERVICE CLASSIFICATION NO. 9 - Continued

TRANSPORTATION SERVICE - Continued

Miscellaneous Provisions - Continued

(D) Curtailments of Service - Continued

The Customer shall permit Company representatives access to the Customer's premises at any time without prior notice to inspect the Customer's facilities and equipment to:

- (1) determine whether the Customer is using gas during a service interruption, or
- (2) verify the accuracy of the meter or the condition of the remote monitoring equipment or alternate fuel or alternate energy equipment. This inspection shall not satisfy the Customer's obligation to notify the Company of any condition that would prevent the required interruption of gas service and shall not exempt the Customer from any applicable Charges for Unauthorized Use.

(E) Customer Responsibility for Equipment

Interruptible and Off-Peak Firm Customers with dual-fuel equipment must maintain operable dual-fuel facilities and fuel supply that is adequate to enable the Customer to operate satisfactorily those facilities without gas whenever and so long as service under this Service Classification is interrupted. Interruptible and Off-Peak Firm Customers with equipment that operates solely on gas must maintain alternate energy facilities that are adequate to supply the energy requirements of the premises otherwise supplied directly or indirectly by the gas-fired equipment whenever and so long as service under this Service Classification is interrupted. The Company may require the Customer to provide documentation of such dual-fuel or alternate energy facilities, as applicable.

Power Generation Customers must maintain operable Emergency Low Gas Inlet Pressure Trip Switch, Gas Telemetry Equipment, and any other equipment the Company deems necessary to provide service.

(Service Classification No. 9 - Continued on Leaf No. 318.0)

Issued By: <u>Joan S. Freilich, Executive Vice President & Chief Financial Officer, 4 Irving Place, New York, N. Y. 10003</u>
(Name of Officer, Title, Address)